



Environmental Commitments Record (ECR)

DIST-CO-RTE: 02 - TRI - 299 **PM/PM:** 11.200/11.200 **EA/Project ID:** 02-2J530_ / 0221000088

Project Description: Repair rock mesh drapery

Date (Last modification): 3/19/2021

Environmental Planner: Nicole Balkow

Phone: 530-759-3407

Construction Liaison:

Phone:

Resident Engineer:

Phone:

PERMITS

Permit	Agency	Application Submitted	Permit Received	Permit Expiration	Permit Requirements Completed by	Permit Requirements Completed on	Comments
--------	--------	-----------------------	-----------------	-------------------	----------------------------------	----------------------------------	----------

ENVIRONMENTAL COMMITMENTS

CONSTRUCTION

Category	Task and Brief Description	Source	Included in PS&E Package	Responsible Branch/Staff	Action to Comply	Due Date	Task Completed by	Task Completed on	Remarks	Mitigation for significant impacts under CEQA
Biology	The emergency repair project is located next to the perennial McDonald Creek. This creek may contain foothill yellow-legged frogs, southern torrent salamanders, salmonids, northwestern pond turtles, and coastal tailed frog. No construction materials or debris may enter the creek.	Env Doc					_____	_____		
							Signature	Date		
Other	Excess material will be disposed of at a SMARA Pit run by Mercer Fraser.						_____	_____		
							Signature	Date		
Other	If overland access is needed for current emergency repair efforts, the contractor must use the existing, delineated rope path.	Env Doc					_____	_____		
							Signature	Date		